

ABSTRACT

In a method for cutting freeform surfaces, a workpiece is cut by a cutting tool such that a desired freeform surface may be achieved, the cutting tool for cutting purposes being moved 5 along at least one defined cutting path relative to the workpiece. A cutting tool is used, the tool head of which has a greater radius than a tool shank of the cutting tool.